10235 8th Street, Rancho Cucamonga, CA 91730

Report #: T18-017

#### REPORT SUMMARY:

**REPORT #:** 

T18-017

**TESTED FOR:** 

International Window Corporation 1551 Orangethorpe Ave. Fullerton, CA 92831

**SERIES & PRODUCT TYPE:** 

8220 - THERMALLY BROKEN ALUMINUM HORIZONTAL SLIDING WINDOW

**CONFIGURATION:** 

XOX

FRAME SIZE:

3657.60 mm x 1219.20 mm (144.00" x 48.00")

#### **SPECIFICATION:**

NAFS - North American Fenestration Standard/specification for windows, doors, and skylights AAMA/WDMA/CSA 101/I.S.2/A440-11

#### PRIMARY DESIGNATOR:

CLASS R-PG20 3657.60 x 1219.20 mm (144.00 x 48.00 in) Type: HS

**TEST COMPLETION DATE:** February 23, 2018

REPORT DATE: March 2, 2018

## 10235 8th Street, Rancho Cucamonga, CA 91730

Report #: T18-017

1.0 Tested For: International Window Corporation

1551 Orangethorpe Ave. Fullerton, CA 92831

#### 2.0 Purpose:

The purpose of this report is to present the testing methods employed and the test results obtained during the performance testing of one (1) THERMALLY BROKEN ALUMINUM HORIZONTAL SLIDING WINDOW described in paragraph 4.0 of this report.

#### 3.0 Test References:

- 3.1 NAFS North American Fenestration Standard/specification for windows, doors, and skylights AAMA/WDMA/CSA 101/I.S.2/A440-11
- **4.0 Compliance Statement:** The test results in paragraph 6.0 indicate that the test sample described in paragraph 5.0 of this report met the performance requirements of the above specifications for the performance grade shown in 4.1 below.
- **4.1** CLASS R-PG20 3657.60 x 1219.20 mm (144.00 x 48.00 in) Type: HS
- 5.0 Sample Submitted:
- 5.1 Product Type:

THERMALLY BROKEN ALUMINUM HORIZONTAL SLIDING

WINDOW

5.2 Series:

5.4

8220 Horizontal Sliding Window

5.3 Configuration:

Product Dimensions:

Millimeters

Inches

Total Frame:

3657.60 x 1219.20

144.00 x 48.00

Fixed DLO:

1768.60 x 1127.25

69.63 x 44.38

**Active Sashes** 

(each):

920.75 x 1171.70

36.25 x 46.13

5.5 Glass and Glazing:

IGU Thickness	Spacer Type	Interior Lite	Exterior Lite	Glazing method
Active sash 0.69"	Metal "U" shaped	SS Annealed	SS Annealed	Channel glazed with wrap around vinyl gasket; the active lite was glazed to the stiles and rails
overall wide	Shapeu	Timicaica	Timeaica	the active lite was glazed to the stries and rans
Fixed Lite	Metal "U"	1/8"	1/8"	Channel glazed with wrap around vinyl gasket;
0.74"	shaped	Annealed	Annealed	the fixed lite was glazed to the frame head, sill,
overall wide				and fixed interlocks.

5.6 Weepage:

Drainage Method	Size	Quantity	Location
Rectangular weep	1.7" x 0.25"	Six (6)	Sill outside face - 2.5", 33.5", and 38.5" from
			each end. Each rectangular weep on the outside face contained a gated weep cover insert.
Rectangular weep	0.63" x 0.09"	Six (6)	Sill outside face to drain the fixed channel – 0.88", 35" and 37" from each end.

#### 5.7 **Pressure balancing:** None

## 10235 8th Street, Rancho Cucamonga, CA 91730

Report #: T18-017

5.8 Weather-stripping:

Туре	Quantity	Location
0.230" overall high polypile	One (1) strip per	Active sashes - one strip full perimeter facing
with center fin	active sash	out per sash.

#### 5.9 Sealants:

Sealant was applied at the following locations:

- 1. All frame corners full profile.
- 2. Fixed interlocks to frame head and sill full profile.
- 3. Jamb to Sill frame corner screws and sill fixed interlock screws were sealed.

#### 5.10 Hardware:

OIZO HAIRIUNGIO		
Туре	Quantity	Location
Metal cam lock	One (1) per	Each acitve sash lock stile - lock was fastened at mid-span
	active sash	with a pair of #8 x 0.5" square drive PH screws. When locked,
		the tongue of the lock engaged a groove on the fixed interlock.
Single adjustable nylon	Two (2) per	At bottom of each active panel stile - each roller fit into a
roller in aluminum housing	active sash	hollow in its respective stile extrusion and fastened with a
		pair of #8 x 0.38" Phil Truss Head screws. The screws went
		through slotted holes in the stile that allowed for adjustment
		of the rollers.
PVC snap-in anti-lift, 3/8"	One (1) per	Head at mid-span of each active sash
	active sash	
There was a secondary loo	k at the bottor	n of each lock stile that was left unengaged during all testing.

#### I here was a secondary lock at the bottom of each lock stile that was left unengaged during all testing.

#### 5.11 Construction:

Location	Joinery Type	Number of Fasteners	Fastener Size
Frame corners	Mechanically joined	Two (2) per corner	#6 x 1" Phil Oval Head Screws
Active sash lead stiles	Mechanically joined	One (1) per corner	#6 x 1.5" PPH
to rails			
Active sash lock stiles	Mechanically joined	One (1) per corner	#6 x 2" PPH
to rails			
Fixed interlocks to	Mechanically joined	One (1) at each end of	#8 x 0.5" PPH
frame	and coped	each fixed interlock	

#### 5.12 Reinforcement: None

#### 5.13 Installation:

Location on frame	Anchor type	Spacing
Full perimeter through the nail-on fin	#8 x 1.5" PFH	3" from each end and 10" on center; Wood furring applied over the nail-on fins and fastened with screws to the rough opening.

**6.0 - Test procedures and results:** All testing procedures were performed in accordance with the performance requirements of the test specifications referenced in paragraph 3.0 of this report. The number preceding each test listed below refers to the corresponding section in the NAFS.

## 10235 8th Street, Rancho Cucamonga, CA 91730

Report #: T18-017

9.3.1 - Operation Force (ASTM E2068-00(2016))

Test Description	Results	Allowed	Comments
Maximum force to initiate motion	61.38 N (13.80 lbf)	Report only	
Maximum force to maintain motion	30.38 N (6.83 lbf)	90 N (20.23 lbf)	
Latching device force	8.89 N (2.00 lbf)	100 N (22.48 lbf)	

9.3.2 - Air Infiltration (ASTM E283-04(2012))

Test Description	Results	Allowed	Comments
75 Pa differential pressure	1.45 L/s*m <sup>2</sup>	1.5 L/s*m <sup>2</sup>	
1.57 psf differential pressure	0.29 cfm/ft <sup>2</sup>	0.30 cfm/ft <sup>2</sup>	
The tested specimen meets the perfor leakage resistance.	mance levels specified in A	AAMA/WDMA/CSA 101/I.S	5.2/A440 for air

9.3.3 - Water Penetration (ASTM E547-00(2016))

Test Description	Results	Allowed	Comments
DP20 - 150 Pa (3.13 psf)	No water penetration	No water penetration	1

9.3.4.2 - Uniform Load Deflection at Design Pressure (ASTM E330-14)

<b>Test Description</b>	Results	Allowed	Comments
DP20 - 960 Pa (20.05 psf) Pos	5.33 mm (0.21")	Report only	2
DP20 - 960 Pa (20.05 psf) Neg	5.84 mm (0.23")	Report only	2

9.3.4.3 - Uniform Load Structural Overload (OL) at 1.5 x Design Pressure (ASTM E330-14)

<b>Test Description</b>	Results	Allowed	Comments
OL for DP20 - 1440 Pa (30.08 psf) Pos	0.51 mm (0.02")	4.57 mm (0.18")	2
OL for DP20 - 1440 Pa (30.08 psf) Neg	0.76 mm (0.03")	4.57 mm (0.18")	2

#### 9.3.5 - Forced Entry Resistance (ASTM F588-14 & CAWM 301-90(1995)) - See comment #3 below

9.3.6.3 - Deglazing Test

<b>Test Description</b>	Results	Allowed	Comments
Active Sash Pull Stile - 320 N (71.94 lbf)	10%	Less than 90% of glazing bite	
Active Sash Rail - 230 N (51.71 lbf)	6%	Less than 90% of glazing bite	

Comment #1 - Tested with and without insect screen in place.

Comment #2 - Deflection measurement taken from fixed interlock.

Comment #3 – Refer to FTL report T17-010 for testing conducted on an identical window containing an active sash equal to or larger in both dimensions than the active sash reflected in this report and that contained a single cam lock on the sash.

Testing was witnessed by: Jim Cruz (FTL).

For a complete description of the tested sample, refer to the attached twenty-five (25) pages consisting of bill of materials, cross section drawings, and die drawings. This report is complete only when all the above referenced bill of materials and drawings are attached.

The bill of materials, cross section drawings, and die drawings of frame and sash members are on file and have been compared to the sample submitted. Test sample sections, bill of materials, drawings and a copy of this report will be retained at the test laboratory for four years.

This test report may not be modified in any way without the written consent of Fenestration Testing Laboratory, Inc (FTL).

# Fenestration Testing Laboratory, Inc. 10235 8th Street, Rancho Cucamonga, CA 91730

Report #: T18-017

The preceding test results relate only to the tested specimen and were obtained by using the applicable test methods listed in section 3.0 and 6.0 above. This report does not constitute certification of this product or an endorsement by this laboratory. It is the property of the client named in section 1.0 above. Certification can only be granted by an approved administrator and/or validator.

Test Completion Date: February 23, 2018

Report Completion Date: March 2, 2018

Pete Cruz - Test Engineer

Jim Cruz - Laboratory Manager